
CITY OF TOPEKA UTILITIES DEPARTMENT

STORMWATER MODEL



Watershed Level of Service


- Scoring 1-5 (1-best, 5-worst)
- Nuisance Flooding
- Cost of Damage
- Number of Population Affected
- Community Impact (schools, hospitals)

Conveyance System Level of Service

- Scoring 1-5 (1-best, 5-worst)
- Applies to Channels and Pipes
- Material (CMP, RCP)
- Remaining Useful Life
- Collateral Damage
- Controlling Storm Event (10-100)

Watershed Score

 Each Watershed Numerically Ranked (1-89)
Based on Composite Watershed and Conveyance System Score




Pipe Segment Score

 Each Pipe Segment Ranked on the Conveyance System Level of Service Factors (1-best, 5-worst)

SW Sunse			Curros 1			1, 1, 10, 0 1, 10, 1 1, 10, 1 1, 10, 1
⊕ Zoom to ⊕ Pan		SW 18th St	1	100 0	- 62 5 15	SW 1.tn st
Stormwater Assets		×	Ave	idanal idanal		Chesney Park
Watershed	84		10000			SW 19th St
Material (Durability)	1	Washbum University	ashburn	ane St (1000 10000		anan
Erosion	1	University A B	Ma	Hadan Cott		Buchanan Diar St
Collateral Damage	1		s	SW		MS 20th St
Remaining Service Life	1	· · · · · · · · · · · · · · · · · · ·	9.190	(Dimostal)	8448	SW 20th St
Controlling Storm Event	1	SW Durow Rd	1 5. 8	8 ° E		
Increase In Demand	1		and the second second			V Hampton St
o Met SW SW 21st	SW Wayne Av	SW 21st St	E o B		1995 1995	

Pipe Physical Attributes

 Provides Pipe Information Including Material, Size, and Installation Date.



QUESTIONS?